Please delete the second paragraph (italicized) on page 5 of the specification.

Please delete the third paragraph (italicized) on page 5 of the specification.

Please delete the second paragraph on page 6 and replace by the following:

--

Here the female mold like undercut zone 6 is a rear undercut with re-entrant angle, which female mold like undercut zone 6 serves for receiving the male like undercut zone 7 of the shoulder 4, wherein the undercut zone 4 is formed nearly sharp edged.

--

Please delete the fourth paragraph on page 6 and replace by the following:

--

The side 4 is situated in an angle of from about 40 to 50 degrees relative to side 2. The side 6 is disposed perpendicular to the side 5.

--,

S.N: 10/757,691 RTZ204A2 March 31, 2006 Page 2

Please delete the second paragraph on page 7 and replace by the following:

--

The geometric kind of the undercut zones 6 and 7 is furnished such at any rate that a slipping in of the zone 4 into the zone 6 is performed as complete as possible.

--

Please delete the fifth paragraph on page 6 and replace by the following:

--

The roof is laid from the bottom to the top during the placement work in such a way as this is shown in detail in figure 3.

--

S.N: 10/757,691 RTZ204A2 March 31, 2006 Page 3